

# Interim Reclamation and Stormwater Inspection

May 16, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

API: 05-001-09805

Adams County, CO

NENE Section 35 T3S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 1.** Well sign at location entrance.



**Photo 2.** Photo taken from the entrance of location, facing Northwest. Inlet protection installed in conjunction with the culvert.

Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 3.** Photo taken from the entrance of location, facing South. Outlet protection installed in conjunction with the culvert.



**Photo 4.** Photo taken from the entrance of location, facing North. Perimeter fence has been adjusted to reduce the disturbance area (red-dashed line) and make more land available to farm.



Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 5.** Photo taken from the northeastern perimeter of the location, facing North. Wattle BMPs have been repaired/replaced around the sediment trap BMP.



**Photo 6.** Photo taken from the northeastern perimeter of the location, facing South. Sediment trap BMP installed with outlet protection device BMPs.

Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 7.** Photo taken from the northern perimeter of the location, facing West. Perimeter fence has been adjusted to reduce the disturbance area (red-dashed line) and make more land available to farm.



**Photo 8.** Photo taken from the northwestern perimeter of the location, facing Southwest. Wattle BMPs along the perimeter of the location have been repaired/replaced.



Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 9.** Photo taken from the western perimeter of the location, facing South. Wattle BMPs along the perimeter of the location have been repaired/replaced.



**Photo 10.** Photo taken from the southwest perimeter of the location, facing Southeast. Perimeter fence has been adjusted to reduce the disturbance area (red-dashed line) and make more land available to farm. Appears this portion of the location was where topsoil was previously. Topsoil was used during the interim reclamation work.



Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 11.** Photo taken from the southern perimeter of the location, facing East. Perimeter fence has been adjusted to reduce the disturbance area (red-dashed line) and make more land available to farm.



**Photo 12.** Photo taken from the southeastern perimeter of the location, facing Northeast. Perimeter fence has been adjusted to reduce the disturbance area (red-dashed line) and make more land available to farm.



Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 13.** Photo taken from the north-facing topsoil stockpile. Canada thistle (*Cirsium arvense*) was observed in small amounts.



**Photo 14.** Photo taken from the southwestern perimeter of the location, facing Northeast. It appears portions of the production area could have been further reduced in size- see following photos.



Inspection Photos  
Location Name: Reserve 3-65 34-35 #1H  
API: 05-001-09805



**Photo 15.** Photo taken from the topsoil stockpile, facing Northeast. Photo illustrates the equipment and facilities on along the production areas.



**Photo 16.** Photo taken from the topsoil stockpile, facing North. Photo illustrates areas along the western production area that do not appear to be necessary for production activity (highlighted in red). If this area is not needed for production activities, the area should comply under Rule 1003.b.