

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

05/19/2017

Document Number:

680601537

**FIELD INSPECTION FORM**

Loc ID 326516 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Hixon, Logan	(505) 386-8018	logan_hixon@xtoenergy.com	
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	All Inspections
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89129	WELL	PR	01/01/2003	GW	067-08233	HUBER-RHOADES 4-33	RI

**General Comment:**

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

**Inspected Facilities**

Facility ID: 89129    Type: WELL    API Number: 067-08233    Status: PR    Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by ponderosa pine woodland and Gambel's oak shrubland. Revegetation is progressing with grasses within the interim reclamation area.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003b. Area no longer in use?      In      Production areas stabilized ?     

1003c. Compacted areas have been cross ripped?     

1003d. Drilling pit closed?      Subsidence over on drill pit?     

Cuttings management:     

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?      In     

Production areas have been stabilized?      Segregated soils have been replaced?     

RESTORATION AND REVEGETATION

Cropland

Top soil replaced      Recontoured      Perennial forage re-established     

Non-Cropland

Top soil replaced      Recontoured      80% Revegetation     

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%     

TRANSECT RESULTS OF REFERENCE AREA%     

TOTAL % OF DESIRABLE VEGETATION COVER     

VEGETATIVE COVER     

1003 f. Weeds Noxious weeds?     

Comment Approximately 1000 Canada thistles are growing within the eastern and southeastern portion of the project area.

Corrective Action Control weeds in the project area.

Date 06/23/2017

Overall Interim Reclamation      In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:      Date Final Reclamation Completed:     

Final Land Use:     

Reminder:     

Comment:

Well plugged      Pit mouse/rat holes, cellars backfilled     

Debris removed      No disturbance /Location never built     

Access Roads      Regraded      Contoured      Culverts removed     

Gravel removed     

Location and associated production facilities reclaimed      Locations, facilities, roads, recontoured     

Compaction alleviation      Dust and erosion control     

Non cropland: Revegetated 80%      Cropland: perennial forage     

Weeds present      Subsidence     

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%     

TRANSECT RESULTS OF REFERENCE AREA%     

TOTAL % OF DESIRABLE VEGETATION COVER     

VEGETATIVE COVER     

Comment:

Corrective Action:

Date     

Overall Final Reclamation      Well Release on Active Location  Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <span style="color: blue;">Stormwater erosional channels are forming within the eastern and southeastern portion of the project area. See attached photos.</span>						Date: <u>06/23/2017</u>
Corrective Action: <span style="color: red;">Stormwater controls need to be installed to stabilize erosion in the eastern and southeastern portion of the project area.</span>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601538	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151811">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151811</a>