



**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 436336 Type: WELL API Number: 123-39053 Status: PR Insp. Status: PR**Complaint**Comment: [2nd attempt to conduct sound survey. Wind velocity greater than 5 MPH. Will attempt again when conditions permit.](#)

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

[2nd attempt to conduct sound survey. Wind velocity greater than 5 MPH. Will attempt again when conditions permit.](#)

carlilec

05/23/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 674005210    | Weather data. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153524</a> |