

Flowline Inspection Photos
Location Name: Orr #24-1
API: 05-123-14538



Photo 1: Pressure test on supply line for ECD



Photo 2: Pressure test for flare line on ECD

Flowline Inspection Photos
Location Name: Orr #24-1
API: 05-123-14538



Photo 3: Risers at wellhead. Unused line marked for removal.



Photo 4: Risers at tank battery.

Flowline Inspection Photos
Location Name: Orr #24-1
API: 05-123-14538



Photo 5: Risers in separator

Photo 6: Risers at separator

Flowline Inspection Photos

Location Name: Orr #24-1

API: 05-123-14538



Photo 1: Risers at ECD