

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2017

Submitted Date:

05/18/2017

Document Number:

682402113**FIELD INSPECTION FORM**Loc ID 438066 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10611Name of Operator: LONGS PEAK RESOURCES LLCAddress: 2323 S SHEPHERD SUITE 1150City: HOUSTON State: TX Zip: 77019**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Clarkson, David		dclarkson@vrtxep.com	
GEISER, EDWARD	(713) 335-4730	egeiser@juncap.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438065	WELL	PR	08/15/2014	OW	123-39863	RAILAY 28-3-1CH	RI

General Comment:

This is a follow up stormwater and reclamation inspection to FIR Document #682401961. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

Appears the accumulation of Russian thistle observed along the eastern fence line has been removed and only small portions remain. Dalmatian toadflax (*Linaria dalmatica*) and Canada thistle (*Cirsium arvense*), both List B Colorado Noxious weeds, were observed at location and need to be controlled to prevent further spreading. Use best available BMPs to control noxious weeds.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

PW/CO

Separator

<= 1 bbl

Comment:

It appears the impacted soil around the equipment along the southeast production area has not been removed. Removal of 1"-2" of gravel on top reveals stained soil with a hydrocarbon like odor.

Corrective Action:

Remove or remediate stained soil. Corrective action date of 5/3/17 remains open until resolved.

Date: 05/03/2017

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	438065	Type:	WELL	API Number:	123-39863	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR, reclamation and stormwater inspection.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: <u>RANGELAND</u>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
	Contoured _____
	Culverts removed _____
	Gravel removed _____
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	Date _____

Overall Final Reclamation ☐ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Sediment Traps	Fail					Need to install outlet protection-see comments
Blankets	Pass					
Ditches	Pass					

Comment: Gully and rill erosion observed along the southern well pad perimeter. Sediment appears to be contained within the stormwater BMP areas of the location. Sediment traps do not have any stabilized outlet protection to prevent sediment laden stormwater from discharging if the sediment trap reaches to capacity. The Operator appeared to be mobilizing equipment to address the issues observed while on location during the inspection.

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 06/15/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to the attached inspection photos in Document #682402114.	binschusc	05/18/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401287500	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4150999
682402114	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4150998