

Inspection Photos
Location Name: McCarty #28-1
API: 05-123-12931




Photo 1: Pressure test of flowline



Photo 2: Risers in separator house

Inspection Photos
Location Name: McCarty #28-1
API: 05-123-12931



Photo 3: Risers at tank battery



Photo 4: Risers at wellhead

Inspection Photos
Location Name: McCarty #28-1
API: 05-123-12931



Photo 5: Risers at separator



Photo 6: Risers at eCD

Inspection Photos
Location Name: McCarty #28-1
API: 05-123-12931



Photo 7: Risers from removed separator.