

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2017

Submitted Date:

05/25/2017

Document Number:

679700451**FIELD INSPECTION FORM**

Loc ID 422931 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422931	LOCATION	AC	04/28/2011		-	Peppler PC AA 18-23 Tank	EI

**General Comment:**

COGCC Environmental Staff Inspection - Peppler 18-41,44;17-32 Tank Battery

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

# 3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		40.487700,-104.472720

Comment: Fiberglass vessel has floated and is displaced. Location is shut-in. See comment at end of this inspection report.

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Adequate

Comment: Liner appears compromised beneath produced water vessel. See comment at end of this inspection report.

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		40.487720,-104.472680	
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shared with ASTs and PBFV						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.487730,-104.472560	
Comment: GPS SE corner of eastern AST						
Corrective Action:					Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:

Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 422931    Type: LOCATION    API Number: -    Status: AC    Insp. Status: EI

**COGCC Comments**

Comment	User	Date
Fiberglass produced water vessel Tank has floated and is displaced. Location is shut-in. COGCC notes that the Pepler 17-32 has been PA and the Pepler 18-41 and 18-44 are both TA. COGCC contacted Operator who confirmed that produced water vessel is empty. If production equipment is abandoned, perform assessment of buried produced water vessels in accordance with Rule 905 and approved Remediation Project #9127 and report results to COGCC. If site is returned to production, repair produced water vessel and ensure integrity of all associated piping prior to returning equipment to production. Maintain record of integrity tests.	allisonr	05/25/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700452	Produced Water Vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156420">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156420</a>
679700453	Compromised Liner	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156421">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156421</a>
679700454	Produced Water Vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156422">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156422</a>
679700455	Produced Water Vessel Piping	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156423">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156423</a>