

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2017

Submitted Date:

05/24/2017

Document Number:

674200078**FIELD INSPECTION FORM**

Loc ID 332541 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248141	WELL	SI	02/01/2017	GW	123-15939	HSR-FROMHOLZ 4-2A	EG
281208	WELL	SI	01/01/2017	GW	123-23355	MILE HIGH 30-2	EG
281209	WELL	SI	01/01/2017	GW	123-23354	MILE HIGH 31-2	EG

General Comment:

[2017 Flowline NTO Inspection](#)
[Shadowing Operator turn on team](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	WIRE		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	

Equipment:

		corrective date
Type: Flow Line	#	
Comment:	4-2" sSTEEL CONNECTED IN USE AT TANK BATTERY	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:	SE CORNER OF SEPARATOR BERMS 40.25948 -104.75334	
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:	1-2" STEEL RISER AT PRODUCED WATER TANK NOT IN USE AND NOT MARKED OR LOCKED OUT OR TAGGED OUT PER NOT SEE ATTACHED PHOTO 40.25922 - 104.75336 TANK BATTERY SE CORNER	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Flow Line	#	
Comment:	MARKED AND FLAGGED PRIOR TO INSPECTION 10- 2" STEEL RISERS IN USE AT SEPERATOR 6 1" STEEL RISERS IN USE AT SEPERATOR 2-2" STEEL RISERS IN USE AT METER RUNS 1-1"STEEL RISER IN USE AT ECD	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.259220,-104.753360
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		40.259220,-104.753360	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: <u>248141</u>	Type: <u>WELL</u>	API Number: <u>123-15939</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:			Date:	
<u>BradenHead</u>				
Comment: <u>PLUMBED TO SURFACE AND PRESSURE MONITORED W/SCADA</u>				
Corrective Action:			Date:	
Facility ID: <u>281208</u>	Type: <u>WELL</u>	API Number: <u>123-23355</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:			Date:	
<u>BradenHead</u>				
Comment: <u>PLUMBED TO SURFACE AND PRESSURE MOINTORED W/SCADA</u>				
Corrective Action:			Date:	
Facility ID: <u>281209</u>	Type: <u>WELL</u>	API Number: <u>123-23354</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
<u>Producing Well</u>				
Comment: <u>PR</u>				
Corrective Action:			Date:	
<u>BradenHead</u>				
Comment: <u>PLUMBED TO DURFACE AND PRESSURE MONITORED W/ SCADA</u>				
Corrective Action:			Date:	
<u>Flowline</u>				
#1	Type: <u>Process Piping</u>	of Lines		
<u>Flowline Description</u>				
Flowline Type: <u>Process Piping</u>		Size: <u>2"</u>	Material: <u>Carbon Steel</u>	
Variance: <u>No</u>		Age:	Contents: <u>Other</u>	
<u>Integrity Summary</u>				
Failures: <u>External Corrosion</u>		Spills: <u>No</u>	Repairs Made: <u>No</u>	
Coatings: <u>Yes External</u>		H2S:	Cathodic Protection:	
<u>Pressure Testing</u>				
Witnessed:		Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>				
<input type="checkbox"/> 1101. Installation and Reclamation		<input type="checkbox"/> 1102. Operations, Maintenance, and Repair		<input type="checkbox"/> 1103. Abandonment
Comment: <u>NO MARKING</u>				
Corrective Action:			Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200079	PHOTOS OF LOCATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156504