

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

05/25/2017

Document Number:

674200090**FIELD INSPECTION FORM**

Loc ID 332275 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**23 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271501	WELL	PR	10/01/2014	OW	123-22071	CANNON LAND 10-11	EG

**General Comment:**

[2017 Flowline NTO Inspection Statewide](#)  
[Shadowing Operator Pressure Testing Team](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	WIRE		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 4		
Comment:	1" STEEL RISERS NOT MARKED 40.14774 -104.73927		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	POINT A AT WELL HEAD 1-1" STEEL RISER MARKED AND CAPPED OFF PER NTO POINT B @ FACILITY		
Corrective Action:		Date:	
Type: Flow Line	# 10		

Comment:		3" POLY RISERS IN USE AT TANK BATTERY		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 2				
Comment:		3" STEEL RISERS @ECD'S 40.14774 -104.73927		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 4				
Comment:		2" STEEL RISER MARKED AND CAPPED OFF FOR ABANDONMENT 40.14774 - 104.73927		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:		3" STEEL RISER NOT MARKED 40.14774 -104.73927		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 18				
Comment:		2" STEEL RISERS IN USE ON LOCATION 40.14774 -104.73927		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 9				
Comment:		2" STEEL RISERS NOT MARKED 40.14774 -104.73927		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Flow Line	# 15				
Comment:		1" STEEL RISERS MARKED AND CAPPED OFF FOR ABONDONMENT 40.14774 - 104.73927		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:		3" STEEL RISES @ SEPERATORS IN USE		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 5				
Comment:		1" STEEL RISER AT ECD ON SOUTH END OF LOCATION IN USE 40.14696 - 104.73946		Date:	
Corrective Action:				Date:	
Type: Flow Line	# 14				
Comment:		2" STEEL RISERS AT TANK BATTERY IN USE		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Flow Line	# 5				

Comment:	3" SALES LINE IN USE DURING PRESSURE TEST 40.14774 -104.73927		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 8			
Comment:	1" STEEL RISERS IN USE 40.14774 -104.73927		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 8			
Comment:	2" FLOW LINE RISERS IN USE DURING PRESSUE TEST 40.14774 -104.73927		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		40.147200,-104.739360
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Insufficient	Adequate
Comment:	PRODUCE WATER TANK BASE NEEDS REPAIR			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	11	300 BBLs	CENTRALIZED BATTERY		40.147200,-104.739360
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 271501 Type: WELL API Number: 123-22071 Status: PR Insp. Status: EG**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: PLUMBED TO SURFACE PRESSURE MONITORED BY SCADA W/PRESSURE  
TRANSDUCER

Corrective Action:

Date:

**Flowline**

#1 Type: Sales Line

of Lines

Flowline DescriptionFlowline Type: Sales LineSize: 2"Material: Carbon Steel

Variance:

Age:

Contents: Crude OilIntegrity Summary

Failures:

Spills: NoRepairs Made: No

Coatings:

H2S: NoCathodic Protection: NoPressure TestingWitnessed: Yes

Test Result:

Charted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200092	PHOTOS OD RISERS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156509</a>
674200097	ANADARKO PRESSURE TEST	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156510">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156510</a>