

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

05/25/2017

Document Number:

675103629**FIELD INSPECTION FORM**
 Loc ID 335329 Inspector Name: GRANAHAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266558	WELL	SI	01/01/2017	GW	045-09152	KELL 35-4D (B35NW)	EG
266568	WELL	PR	02/19/2004	GW	045-09155	KELL 35-4A (B35NW)	EG
266572	WELL	PR	09/27/2003	GW	045-09158	KELL 35-3D (B35NW)	EG
266573	WELL	PR	02/19/2004	GW	045-09157	KELL 35-3B (B35NW)	EG

General Comment:2017 Flowline NTO inspection 1000' buffer

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	39.48869/-107.74248		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE; 4-3" steel risers from wells to separators. 4-3" steel risers from gas out separator to sales line. 4-2" steel risers from separator water/oil dump to tank battery. 1-2" steel riser from separator gas out to gas meter sales. 3-3" steel risers from separator water/oil dump to tank battery.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	No not in use flow lines identified on location		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		

Comment:	39.48860/-107.74245		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.488390,-107.742330	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 266558 Type: WELL API Number: 045-09152 Status: SI Insp. Status: EG**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SI - no leaks/venting -braden head & remote pressure monitoring present.Corrective Action: Date: Facility ID: 266568 Type: WELL API Number: 045-09155 Status: PR Insp. Status: EG**Producing Well**Comment: PR - via plunger lift, no leaks/venting - bradenhead & remote pressure monitoring presentCorrective Action: Date: Facility ID: 266572 Type: WELL API Number: 045-09158 Status: PR Insp. Status: EG**Producing Well**Comment: PR - no leaks/venting - bradenhead & remote pressure monitoring presentCorrective Action: Date: Facility ID: 266573 Type: WELL API Number: 045-09157 Status: PR Insp. Status: EG**Producing Well**Comment: PR - via plunger lift, no leaks/venting - bradenhead & remote pressure monitoring presentCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
Gravel	Pass					
Compaction	Pass					
Berms	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103630	Flowline photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156536