

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2017

Submitted Date:

05/26/2017

Document Number:

679600110**FIELD INSPECTION FORM**

Loc ID 320206 Inspector Name: HICKEY, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 87195Name of Operator: TEXAS TEA OF COLORADO LLC DBA TEXAS TEA LLCAddress: 14405 W. COLFAX #298City: LAKEWOOD State: CO Zip: 80401**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

General Comment:

2017 Flowline NTO inspection
ODO well in process for abandonment

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

1

Comment: Flowline from wellhead to battery is live.

Corrective Action: Date:

Type: Flow Line

9

Comment: Flowline risers at separator location are bull plugged with no valves to relieve pressure. They may be manifolded with in use lines on site.

Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	<50 BBLs	STEEL AST		36.965020,104.865030	
Comment: previous tanks and separators were either common or removed.						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

Paint

Condition	
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				
Date: <input type="text"/>				

Venting:

Yes/No	NO		
Comment: <input type="text"/>			
Corrective Action: <input type="text"/>		Date: <input type="text"/>	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
Wellhead flowline appears to still have pressure on it. Separator location flowlines may be manifolded to existing lines. Bull plugs without P/R valves may require "hot tap" to determine if they are under pressure.	hickeymi	05/26/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600111	Nauman Photos at wellhead and battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156962