

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

05/26/2017

Document Number:

685303170

FIELD INSPECTION FORM

Loc ID 326275 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16695
Name of Operator: CHEVRON MIDCONTINENT LP
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pohl, April	505-333-1941	april.pohl@chevron.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216152	WELL	PR	02/04/2000	GW	067-07758	LAPALOMA 1-2	PR

General Comment:

2017 Flowline NTO Inspection
See link at end of report for path to downloadable pictures. This inspection does not alleviate requirement to complete any open corrective actions from previous inspections. Inspection report contains corrective action and comment. See Signs/Marker section of report for additional details.

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel two track road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	No sign or label for tank contents, tank capacity, or NFPA.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/26/2017
Type	CONTAINERS		
Comment:	Label on chemical tank is faded and unreadable.		
Corrective Action:	Install label or signage to comply with Rule 210.d.(2).	Date:	07/26/2017
Type	WELLHEAD		
Comment:	Free standing framed metal sign at location entrance.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign at location entrance.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	6' chain link fence panels.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' chain link fence panels.		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Prime Mover	# 1	
Comment:	Electric motor.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Electrical service equipment.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 3	
Comment:	Flowlines for 067 07758 Lat/Long 37.240896/-107.805797 In use 6" steel line from wellhead casing (A) to separator (B). In use 3" steel line from wellhead tubing (A) to separator (B). In use 3" steel above ground water dump line from separator (A) to tank (B).	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Wellhead.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry equipment.	
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:	Flowlines for 067 07758 Lat/Long 37.240896/-107.805797 Not in use - 1" return supply gas line from separator (A) to wellhead (B).	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank and pump on spill prevention.	
Corrective Action:		Date:
Type: Vertical Heated Separator	#	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	All in one unit.	
Corrective Action:		Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.144520,-107.483260
Comment: Open top tank with expanded metal cover and earthen berms.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)	No signage or label.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 216152 Type: WELL API Number: 067-07758 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Review of electronic well file reflects last reported production as March 2017.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location located on ridge with cut and fill slopes. Pad surrounded by Juniper and Pinion trees.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gradient Terraces	Pass	Gravel				
Sediment Traps	Pass					
Rip Rap	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Chemical tank on spill prevention.
Compaction	Pass	Check Dams	Pass			
Gravel	Pass					

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303177	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157059
685303178	Check dams along access road.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157060
685303179	Rip rap and sediment trap.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157061
685303180	Faded label on chemical tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157062
685303181	Water tank with no capacity or NFPA label.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157063