

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2017

Submitted Date:

05/22/2017

Document Number:

685303104**FIELD INSPECTION FORM**Loc ID 306882 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------|---------------------------------------|
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 273247 | WELL | PR | 07/30/2004 | GW | 067-08955 | TUBBS 32-6-9 B 2 | PR |

General Comment:[See link at end of report for path to downloadable pictures.](#)

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 273247 | Type: | WELL | API Number: | 067-08955 | Status: | PR | Insp. Status: | PR |
| | | | | | | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| Check Dams | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Metal containment around produced water tank. |
| Compaction | Pass | Culverts | Pass | | | |
| Sediment Traps | Pass | | | | | |
| Ditches | Pass | Ditches | Pass | | | |
| Waddles | Pass | | | | | |
| Rip Rap | Pass | | | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective action completed. Additional BMPs maybe required to stabilize slope as small rills are developing in NE corner.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 401289054 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152511 |
| 685303156 | Wellhead sign. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152491 |
| 685303157 | Rip rap and waddle sediment trap 1. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152492 |
| 685303158 | Location overview. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152493 |
| 685303159 | Developing rilling in NE corner. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152494 |
| 685303160 | Rip rap repair and sediment traps at base of slope. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152495 |