

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

05/25/2017

Document Number:

670201486**FIELD INSPECTION FORM**

Loc ID 322300 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 73372Name of Operator: RANCHO TRESAddress: BOX BCity: RIFLE State: CO Zip: 81650**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210186	WELL	DM	02/01/1961	GW	045-05083	BERT EATON 1	DM

**General Comment:**

Inspection for potential plugging and abandonment. Met with landowner Roy Savage on location. Field was wet at time of inspection but Mr. Savage informed that irrigation will be shut off and cattle are out of pasture. Small shed over well will need to be removed. Well is shut in. A 1" flowline was still attached to the well with the valves in the off position and gate valve on well shut. Flowline disconnected by COGCC staff on 5/26/2017. See attached photo of wellhead and diagram of approximate flowline alignment per landowner.

**Inspected Facilities**Facility ID: 210186 Type: WELL API Number: 045-05083 Status: DM Insp. Status: DM**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Bond has been claimed on this orphan well.Corrective Action: Plug and abandon. Date: 06/30/2017**Flowline**

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: Other Material: Poly  
 Variance: Age: Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☒ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Flowline is still attached to the well with the valves in the off position and gate valve on well shut. 1" yellow poly flowline is reportedly not in use and runs approximately 1600 feet along the county road to the stone house to the east.

Corrective Action: Abandon flowline per COGCC rules. Date: 06/30/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
670201492	Flowline Alignment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4157729</a>