

Inspection Photos – 2017 Flowline NTO  
Inspection  
Location Name: Gooch 2-33  
API: 05-081-05366



**Photo 1. Location overview taken at entrance facing southeast.**

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: Gooch 2-33  
API: 05-081-05366



**Photo 2. Stained soil at wellhead.**



**Photo 3. Wellhead assembly showing 1 -2" insulated riser, 1 -1" poly line, methanol lines.**

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: Gooch 2-33  
API: 05-081-05366



Photo 4. Wellhead assembly showing lines running to separator and motor.



Photo 5. Close-up of 2 -1" risers not in use.