

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 1. Overview of location taken at entrance to location facing west.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 2. Concrete base at entrance with 4 – 2" steel risers not in use.



Photo 3. Unlabeled container.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 4. Stained soil at pump jack exhaust.



Photo 5. Wellhead. 2 – 1" steel risers, 1 – 2" steel riser, 1 – 2" steel to poly flowline to 1" steel riser.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 6. 1 – 2” steel riser at tank and pit.



Photo 7. 1 – 2” and 1 -1” steel riser not in use.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 8. 3 – 1” steel risers at horizontal separator.



Photo 9. 5 -2” steel risers and 2 – 1” steel risers at vertical separator.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 10. 5 – 2” steel risers and 3 – 1” steel risers not in use.



Photo 11. 2 – 1” and 1 – 2” steel insulated risers at tank.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Amoco-Federal 21-1
API: 05-081-06439



Photo 12. Pit in tank berm with sheen and oil and two flowlines entering from tank battery.



Photo 13. Close-up of flowlines and sheen and oil on pit.