

Flowline and Final Reclamation Inspection

May 26, 2017

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06112

Larimer County, CO

SESE Section 29 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Google Earth aerial imagery taken June 19, 2014 illustrating an approximate 770' access road AND well location that has not been reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Photo 1. Photo taken from the access point off CO Rd. 16, facing North along the access road. Gravel has not been removed and access road has not been contoured.



Photo 2. Photo taken north of the previous photo location, facing North along the access road. Gravel has not been removed and access road has not been contoured.

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Photo 3. Photo taken north of the previous photo location, facing North along the access road. Gravel has not been removed and access road has not been contoured.



Photo 4. Photo taken north of the previous photo location, facing North along the access road. Gravel has not been removed and access road has not been contoured.

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Photo 5. Photo taken from the well location, facing North. Gravel has not been removed and has not been contoured.



Photo 6. Reference photo taken east of the access road, facing East. Disturbance areas are not reflective of cropland reference areas.