

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2017

Submitted Date:

05/30/2017

Document Number:

673404662**FIELD INSPECTION FORM**
 Loc ID 312970 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223077	WELL	PR	07/31/2003	OW	081-06439	AMOCO-FEDERAL 21-1	PR

General Comment:2017 Flowline NTO Inspection Statewide

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sign not posted or information inaccurate on tanks or containers Container(s) not labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/30/2017
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:	40.89318, -108.29452		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	NOT IN USE: concrete base at entrance (40.89324, -108.29391) with 4 - 2" steel risers 1 - 2" steel riser, 1 - 1" steel riser at 40.89334, -108.29448 riser cluster with concrete base at 40.89309, -108.29463 with 5 - 2" steel risers and 2 - 1" steel riser		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Stained soil at wellhead and exhaust.		

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	10/08/2015
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	#			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	40.89318, -108.29452			
Corrective Action:			Date:	
Type: Flow Line	#			
Comment:	IN USE: 2 - 1" steel riser at wellhead 1 - 2" steel riser at wellhead 1 - 2" steel to poly flowline to 1" steel riser at wellhead 1 - 2" steel riser into pit 3 - 1" steel riser to horizontal seperator 5 - 2" and 2 - 1" steel risers to vertical seperator 2 - 1" insulated steel riser and 1 - 2" insulated steel riser at tank 3 - 1" steel riser, 1 - 1" steel riser at tank 1 - 2" steel flowline and 1 - 2" poly flowline to pit			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		40.893110,-108.294190
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 223077	Type: WELL	API Number: 081-06439	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.893460 Long: -108.294320

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: GPS coordinates for pit with underground tank. Is this pit permitted?

Corrective Action

Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify if this pit is permitted and to permit and close pit if it is not.

Date: 11/24/2016

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.893060 Long: -108.294170

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____

Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh

Netting Condition: Holes

Inspector Name: Waldron, Emily

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>YES</u>	2+ feet Freeboard:
Comment:	GPS coordinates for pit in tank berm. Is this pit ID 112982? Pit has oil sheen and free oil floating on water in it.	
Corrective Action	Remove oil from pit per Rule 902.c.	
	Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify if this pit ID is appropriate and to close pit if not in use or properly permit pit if in use and not associated with the above ID.	
	Date: <u>05/31/2017</u>	

COGCC Comments

Comment	User	Date
Follow up to inspection from 10/12/2016 document number 673403737. All corrective actions remain outstanding.	waldrone	05/30/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404663	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158586