

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2017

Submitted Date:

05/30/2017

Document Number:

666803190

### FIELD INSPECTION FORM

Loc ID 335346 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258296	WELL	PR	09/01/2004	GW	045-07633	JACKSON 15-28	PR
259436	WELL	PR	09/01/2004	GW	045-07725	JACKSON 16-28	PR

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer  
 Shadowing Operator Pressure Testing Team

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 2	Comment: <a href="#">39.492559/-107.669017</a>	Corrective Action:	Date:	
Type: Gas Meter Run	# 2	Comment: <a href="#">At separators</a>	Corrective Action:	Date:	
Type: Emission Control Device	# 1	Comment: <a href="#">39.492524/-107.669237</a>	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 2	Comment: <a href="#">39.492838/-107.669074</a>	Corrective Action:	Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	200 BBLs	STEEL AST		39.492731,-107.669172
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			
				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 258296 Type: WELL API Number: 045-07633 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**Flowline**

#1 Type:Well Site

2 of Lines

Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Natural Gas

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#2 Type:Dump Line

1 of Lines

Flowline Description

Flowline Type: Dump Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Produced Water

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#3 Type:Dump Line

1 of Lines

Flowline Description

Flowline Type: Dump Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Condensate

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

**Pressure Testing**  
 Witnessed: Yes                      Test Result: Pass                      Charted: Yes

COGCC Rules(check all that apply)  
 1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_                      Date: \_\_\_\_\_

#4	Type:Sales Line	2 of Lines
----	-----------------	------------

**Flowline Description**  
 Flowline Type: Sales Line                      Size: 2"                      Material: Carbon Steel  
 Variance:                      Age:                      Contents: Natural Gas

**Integrity Summary**  
 Failures:                      Spills:                      Repairs Made:  
 Coatings:                      H2S:                      Cathodic Protection:

**Pressure Testing**  
 Witnessed:                      Test Result:                      Charted:

COGCC Rules(check all that apply)  
 1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_                      Date: \_\_\_\_\_

#5	Type:Process Piping	1 of Lines
----	---------------------	------------

**Flowline Description**  
 Flowline Type: Process Piping                      Size: Other                      Material: Carbon Steel  
 Variance:                      Age:                      Contents: Natural Gas

**Integrity Summary**  
 Failures:                      Spills:                      Repairs Made:  
 Coatings:                      H2S:                      Cathodic Protection:

**Pressure Testing**  
 Witnessed: Yes                      Test Result: Pass                      Charted: Yes

COGCC Rules(check all that apply)  
 1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: Supply line to ECB  
 Corrective Action: \_\_\_\_\_                      Date: \_\_\_\_\_

Facility ID: <u>259436</u>	Type: <u>WELL</u>	API Number: <u>045-07725</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: Plunger lift  
 Corrective Action: \_\_\_\_\_                      Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Seeding	Pass					
		Culverts	Pass			
Gravel	Pass					
Rip Rap	Pass					
		Ditches	Pass			
		Check Dams	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803193	location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158618">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158618</a>