



**photo 1:** Facing west toward the access road.



**photo 2:** Facing west toward the location.



**photo 3:** There is an electric utility that remains at the location.



**photo 4:** A block remains which can interfere with ag activities.



**photo 5:** West side of the location facing east.



**photo 6:** Facing west at the surrounding crop.