

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
7
API: 05-081-06605



Photo 1. Overview of location taken at entrance to location facing east.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
7
API: 05-081-06605



Photo 2. Risers at wellhead. Stained soil at wellhead.



Photo 3. 1 – 2" steel riser at 40.88615, -108.29376

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
7
API: 05-081-06605



Photo 4. Risers inside stand alone vertical separator.



Photo 5. 3 – 2" steel risers at 40.88588, -108.29424

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
7
API: 05-081-06605



Photo 6. Risers at horizontal separator on east end.



Photo 7. Risers at middle separator.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
7
API: 05-081-06605



Photo 8. Risers and flowlines at vertical and middle horizontal separators.



Photo 9. 2 – 2" steel risers at meter run. Unlabeled container on right.