

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
11
API: 05-081-06425



Photo 1. Overview of location taken at entrance to location facing south.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
11
API: 05-081-06605



Photo 2. Pit at 40.882770, -108.299100.



Photo 3. Risers at wellhead. Lube oil containers stored without secondary containment in background.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
11
API: 05-081-06605



Photo 4. Risers at separator.



Photo 5. Risers at separator with poly flowline in foreground.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
11
API: 05-081-06605



Photo 6. Risers inside separator.



Photo 7. Risers at tank battery.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
11
API: 05-081-06605



Photo 8. Flowlines from tank battery to separator and pit.