

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401278138

Date Received:

05/30/2017

## FIR RESOLUTION FORM

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Herring, Paul

303-727-9915

paul.herring@topoperating.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685502496

Inspection Date: 04/19/2017

FIR Submit Date: 04/19/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

### LOCATION - Location ID: 311313

Location Name: DI-TA (JOHN DITIRRO)-62N66W Number: 30SENW County: WELD

Qtrqtr: SENW Sec: 30 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.111000 Longitude: -104.824530

### FACILITY - API Number: 05-123-00 Facility ID: 241303

Facility Name: DI-TA (JOHN DITIRRO) Number: 2

Qtrqtr: SENW Sec: 30 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.111000 Longitude: -104.824530

### CORRECTIVE ACTIONS:

1 ☒ CA# 71077

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 05/04/2017

Response: CA COMPLETED

Date of Completion: 05/01/2017

Operator Comment: Berm repaired

COGCC Decision: Approved

COGCC Representative: BERM REPAIRED

**2** ☒ CA# 71078

Corrective Action: Install sign to comply with Rule 210.a.

Date: 04/24/2017

Response: CA COMPLETED

Date of Completion: 05/12/2017

Operator Comment: Sign has been installed

COGCC Decision: Approved

COGCC Representative: WELL SIGN INSTALLED

**3** ☒ CA# 71079

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 04/29/2017

Response: CA COMPLETED

Date of Completion: 05/09/2017

Operator Comment: Pipe, placed on location by gravel pit, has been removed. Berm repaired, weeds removed.

COGCC Decision: Approved

COGCC Representative: UNUSED EQUIPMENT REMOVED

**4** ☒ CA# 71080

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 05/19/2017

Response: CA COMPLETED

Date of Completion: 05/01/2017

Operator Comment: Berms have been repaired, weeds have been removed, material placed on location by pit has been removed.

COGCC Decision: Approved

COGCC Representative: BERMS REPAIRED

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: \_\_\_\_\_

Title: Landman

Date: 5/30/2017 3:43:31 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401278138	FIR RESOLUTION SUBMITTED
401278182	Dita 1 and 2 seperator berm
401295839	Dita 1 and 2 tank battery photo 1
401295846	Dita 1A well head
401295849	Dita 1 and 2 tank battery photo 2

Total Attach: 5 Files