

## Flowline Inspection Photos

Location Name: Frank #5

API: 05-123-23186



**Photo 1: Pressure test**



**Photo 2: Risers at wellhead**



**Flowline Inspection Photos**  
**Location Name: Frank #5**  
**API: 05-123-23186**



**Photo 3: Risers at ECD**



**Photo 4: Risers at separator**



**Flowline Inspection Photos**  
**Location Name: Frank #5**  
**API: 05-123-23186**



**Photo 5: Risers in separator**



**Photo 6: Risers in tank battery**