

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

05/25/2017

Document Number:

674200090**FIELD INSPECTION FORM**
 Loc ID 332275 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:23 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271501	WELL	PR	10/01/2014	OW	123-22071	CANNON LAND 10-11	EG

General Comment:

2017 Flowline NTO Inspection Statewide
Shadowing Operator Pressure Testing Team

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	WIRE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 4		
Comment:	1" STEEL RISERS NOT MARKED 40.14774 -104.73927		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	3" POLY RISERS IN USE AT TANK BATTERY		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" STEEL RISERS @ECD'S 40.14774 -104.73927		
Corrective Action:		Date:	
Type: Flow Line	# 4		

Comment:	2" STEEL RISER MARKED AND CAPPED OFF FOR ABANDONMENT 40.14774 - 104.73927			
Corrective Action:			Date:	
Type: Flow Line	# 18			
Comment:	2" STEEL RISERS IN USE ON LOCATION 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 15			
Comment:	1" STEEL RISERS MARKED AND CAPPED OFF FOR ABONDONMENT 40.14774 - 104.73927			
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	3" STEEL RISES @ SEPERATORS IN USE			
Corrective Action:			Date:	
Type: Flow Line	# 14			
Comment:	2" STEEL RISERS AT TANK BATTERY IN USE			
Corrective Action:			Date:	
Type: Flow Line	# 8			
Comment:	2" FLOW LINE RISERS IN USE DURING PRESSUE TEST 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Flow Line	# 8			
Comment:	1" STEEL RISERS IN USE 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Flow Line	# 5			
Comment:	3" SALES LINE IN USE DURING PRESSURE TEST 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 9			
Comment:	2" STEEL RISERS NOT MARKED 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	3" STEEL RISER NOT MARKED 40.14774 -104.73927			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			

Comment:	POINT A AT WELL HEAD 1-1" STEEL RISER MARKED AND CAPPED OFF PER NTO POINT B @ FACILITY				
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 5				
Comment:	1" STEEL RISER AT ECD ON SOUTH END OF LOCATION IN USE40.14696 - 104.73946				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		40.147200,-104.739360
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Insufficient	Adequate
Comment:	PRODUCE WATER TANK BASE NEEDS REPAIR			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	11	300 BBLS	CENTRALIZED BATTERY		40.147200,-104.739360
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 271501 Type: WELL API Number: 123-22071 Status: PR Insp. Status: EG**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: PLUMBED TO SURFACE PRESSURE MONITORED BY SCADA W/PRESSURE
TRANSDUCER

Corrective Action:

Date:

Flowline

#1 Type: Sales Line

of Lines

Flowline DescriptionFlowline Type: Sales LineSize: 2"Material: Carbon Steel

Variance:

Age:

Contents: Crude OilIntegrity Summary

Failures:

Spills: NoRepairs Made: No

Coatings:

H2S: NoCathodic Protection: NoPressure TestingWitnessed: Yes

Test Result:

Charted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401293846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156523
674200092	PHOTOS OD RISERS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156509
674200097	ANADARKO PRESSURE TEST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156510