

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: McWilliams 4-31
API: 05-081-06521



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: McWilliams 4-31
API: 05-081-06521



Photo 2. Wellhead with 1 – 2” riser on right.



Photo 3. Pit with 2” steel flowline entering from separator.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: McWilliams 4-31
API: 05-081-06521



Photo 4. Meter run with 1 – 2” steel riser and separator with 2 -2” steel risers.



Photo 5. Riser cluster with 3 – 2” insulated risers at 40.61391, -107.54092