

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: McWilliams 2-31
API: 05-081-06351



Photo 1. Overview of location taken at entrance facing south.



Photo 2. 1 - 2" steel riser at wellhead.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: McWilliams 2-31
API: 05-081-06351



Photo 3. Pit with separator and meter run and risers.



Photo 4. Riser cluster with 4 – 2” insulated steel risers at 40.61253, -107.52946