

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Carpenter 2-32
API: 05-081-05363



Photo 1. Overview of location taken at entrance facing east.



Photo 2. 3 - 2" steel riser at wellhead.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Carpenter 2-32
API: 05-081-05363



Photo 3. Unlabeled container at wellhead.



Photo 4. Risers at separator and tank.