

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Schieck 11-31
API: 05-081-06530



Photo 1. Overview of location taken at entrance facing north.



Photo 2. 1 – 2" steel riser at wellhead.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Schieck 11-31
API: 05-081-06530



**Photo 3. Riser cluster with 2 – 2” and 1 – 1” steel risers
at 40.60605, -107.53705**



Photo 4. 1 – 2” steel riser at meter run.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Schieck 11-31
API: 05-081-06530



Photo 5. 2 – 2" and 1 – 1" steel risers at separator.



Photo 6. Steel flowline from separator to tank with 1 – 1" steel riser at midway point.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Schieck 11-31
API: 05-081-06530



Photo 7. 1 – 2" steel riser at tank.



Photo 8. Pit.