

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: Government Treleven 6  
API: 05-081-05238



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. 1 - 2" steel riser at wellhead.