

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

673404673**FIELD INSPECTION FORM**
 Loc ID 312949 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: 138 PINYON CIRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone          | Email             | Comment |
|---------------|----------------|-------------------|---------|
| hinaman, gary | (970) 675-8257 | hinaman@lexry.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 222989      | WELL | PR     | 06/27/2013  | GW         | 081-06351 | MC WILLIAMS 2-31 | PR          |

**General Comment:**2017 Flowline NTO Inspection Statewide

**Location**Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD                                    |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | CONTAINERS                                  |       |  |
| Comment:             | 500 gallon methanol<br>1000 gallon methanol |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | BATTERY                                     |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment: 970-629-5536

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PIT       |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |
| Type               | WELLHEAD  |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |
| Type               | SEPARATOR |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

|                                   |                      |       |                 |
|-----------------------------------|----------------------|-------|-----------------|
| <b>Equipment:</b>                 |                      |       | corrective date |
| Type: Deadman # & Marked          | # 4                  |       |                 |
| Comment:                          |                      |       |                 |
| Corrective Action:                |                      | Date: |                 |
| Type: Horizontal Heated Separator | # 1                  |       |                 |
| Comment:                          | 40.61234, -107.52937 |       |                 |
| Corrective Action:                |                      | Date: |                 |
| Type: Gas Meter Run               | # 1                  |       |                 |

|                       |  |       |  |
|-----------------------|--|-------|--|
| Comment:              | 40.61234, -107.52937   |       |  |
| Corrective Action:    |  | Date: |  |
| Type: Bird Protectors | #  |       |  |
| Comment:              |  |       |  |
| Corrective Action:    |  | Date: |  |
| Type: Flow Line       | #  |       |  |
| Comment:              | IN USE: at wellhead: 1 - 2" steel riser<br>at pit: 2 - 2" steel risers and 2 - 2" steel flowlines, one to separator one to meter run<br>2 - 2" steel insulated risers, 2 - 2" steel insulated risers at 40.61253, -107.52946 |       |  |
| Corrective Action:    |  | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 222989         | Type: WELL | API Number: 081-06351 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    |            |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

|                        |              |                       |                       |                          |
|------------------------|--------------|-----------------------|-----------------------|--------------------------|
| Type:                  | Lined:       | Pit ID: <u>112096</u> | Lat: <u>40.613627</u> | Long: <u>-107.531880</u> |
| Reference Point: _____ | Other: _____ | Length: _____         | Width: _____          |                          |

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 673404684    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160868">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160868</a> |