

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2017

Submitted Date:

06/01/2017

Document Number:

673404681**FIELD INSPECTION FORM**

Loc ID 312766 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 95520Name of Operator: WESCO OPERATING INCAddress: 120 S DURBIN STREETCity: CASPER State: WY Zip: 82602**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone        | Email                      | Comment |
|------------------|--------------|----------------------------|---------|
| Kirkwood, Thomas | 307-577-5328 | tomk@kirkwoodcompanies.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 222259      | WELL | PR     | 10/01/1994  | OW         | 081-05228 | TRELEAVEN-GOVERNMENT 3 | PR          |

**General Comment:**[2017 Flowline NTO Inspection Statewide](#)

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: 1-866-965-6296

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PUMP JACK |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

|                          |   |       |                 |
|--------------------------|---|-------|-----------------|
| <b>Equipment:</b>        |   |       | corrective date |
| Type: Flow Line          | #                                       |       |                 |
| Comment:                 | IN USE: 2 - 2" steel risers at wellhead |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Deadman # & Marked | # 4                                     |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Pump Jack          | # 1                                     |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |            |                       |            |                  |
|----------------------|------------|-----------------------|------------|------------------|
| Facility ID: 222259  | Type: WELL | API Number: 081-05228 | Status: PR | Insp. Status: PR |
| Producing Well       |            |                       |            |                  |
| Comment:             | Pumping.   |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 673404692    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160876</a> |