



**photo 1:** There is an area of subsidence going east toward the location.



**photo 2:** Facing west toward the location. The powerline utility terminates at the location.



**photo 3:** Facing east at the location.



**photo 4:** The electric powerline utility terminates at the location.