

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2017

Submitted Date:

05/21/2017

Document Number:

679600106**FIELD INSPECTION FORM**

Loc ID 320257 Inspector Name: HICKEY, MIKE On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 87195Name of Operator: TEXAS TEA OF COLORADO LLC DBA TEXAS TEA LLCAddress: 14405 W. COLFAX #298City: LAKEWOOD State: CO Zip: 80401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203266	WELL	PR	05/15/2001	OW	001-08775	BIOW-MOORE 3-1	IO

**General Comment:**

2017 Floline NTO Inspection  
 ODO well in process for plug and abandonment.

**Inspected Facilities**Facility ID: 203266 Type: WELL API Number: 001-08775 Status: PR Insp. Status: IO**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type: Dump Line	of Lines	
----	-----------------	----------	--

**Flowline Description**Flowline Type: Dump Line Size: 2" Material: Carbon Steel

Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

**Integrity Summary**

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_

Coatings: Yes External H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_**Pressure Testing**

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Flowline risers at seperator and tank battery. See photos.  
Seperator loc per garmin 39.98862/104.86935 (+/- 15 ft N. of seperator)  
battery loc. per garmin 39.98853/104.86904 (w/in secondary containment)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>2017 Flowline NTO Inspection</u> <u>ODO well in process for abandonment.</u>	hickeymi	05/17/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401294187	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156940</a>
679600107	BLOW_Moore photos with labels	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156938">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156938</a>