



Photo 1. View of the tank in the northeastern portion of the project area.



Photo 2. View of discharged oily material appears to be leaking from wellhead.



Photo 3. View of risers in the project area.



Photo 4. View of unused equipment in the project area.