

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2017

Submitted Date:

06/02/2017

Document Number:

682600308

**FIELD INSPECTION FORM**

Loc ID 439367 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10412  
Name of Operator: AUS-TEX EXPLORATION INC  
Address: 113 N SANTA FE  
City: FLORENCE State: CO Zip: 81226

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austinexploration.com	All Inspections
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	SI	06/08/2016	OW	043-06227	Columbus 1	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Operator has improperly stored fluids and non E&P waste leaking on location (see attached photos).

At the time of inspection on 6/1/2017 sediment control BMPs were not installed correctly. Straw wattles have been laid on top of ground, are inadequately staked and will allow runoff to flow under the BMPs.

**Inspected Facilities**

Facility ID: 439366 Type: WELL API Number: 043-06227 Status: SI Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: NON E&P WASTE Estimated Spill Volume: \_\_\_\_\_

Comment: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Corrective Action: Operator shall clean up spill within 48 hours. Date: 06/04/2017

Reportable: NO GPS: Lat 38.314800 Long -105.150702

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Pursuant to Rule 1002.f., Aus-Tex Exploration Inc. shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control storm water runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

At the time of inspection on 6/1/2017 sediment control BMPs were not installed correctly. Straw wattles have been laid on top of ground, are inadequately staked and will allow runoff to flow under the BMPs.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/30/2017

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Follow up inspection required to document spill cleanup and proper installation of sediment control BMPs.	kosolaj	06/02/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600314	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161660</a>