

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2017

Submitted Date:

06/05/2017

Document Number:

680601596**FIELD INSPECTION FORM**Loc ID 326297 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	All Inspections
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	All Inspections
Hixon, Logan	(505) 386-8018	logan_hixon@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216188	WELL	PR	03/16/1993	GW	067-07794	HUBER-LEWIS 2-33	RI

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable. Corrective action dates are based off of when the inspection is submitted.

Inspected Facilities									
Facility ID:	216188	Type:	WELL	API Number:	067-07794	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Revegetation is progressing within the interim reclamation area.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Small pieces of liner material are scattered around the interim reclamation area. These need to be removed.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>In</u>	Production areas stabilized ? <u> </u>
1003c. Compacted areas have been cross ripped? <u> </u>	
1003d. Drilling pit closed? <u> </u>	Subsidence over on drill pit? <u> </u>
Cuttings management: <u> </u>	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? <u> </u>	Segregated soils have been replaced? <u> </u>
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced <u> </u>	Recontoured <u> </u>
Perennial forage re-established <u> </u>	
<u>Non-Cropland</u>	
Top soil replaced <u> </u>	Recontoured <u> </u>
80% Revegetation <u> </u>	
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% <u> </u>	
TRANSECT RESULTS OF REFERENCE AREA% <u> </u>	
TOTAL % OF DESIRABLE VEGETATION COVER <u> </u>	
VEGETATIVE COVER <u> </u>	
1003 f. Weeds Noxious weeds? <u> </u>	
Comment	<u>Approximately 50 musk thistle are growing within the interim reclamation area.</u>
Corrective Action	<u>Control weeds.</u>
	Date <u>07/07/2017</u>
Overall Interim Reclamation	<u>In Process</u>

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: <u> </u>	Date Final Reclamation Completed: <u> </u>
Final Land Use: <u> </u>	
Reminder: <u> </u>	
Comment: <u> </u>	
Well plugged <u> </u>	Pit mouse/rat holes, cellars backfilled <u> </u>
Debris removed <u> </u>	No disturbance /Location never built <u> </u>
Access Roads <u> </u>	Regraded <u> </u>
Gravel removed <u> </u>	Contoured <u> </u>
Culverts removed <u> </u>	
Location and associated production facilities reclaimed <u> </u>	Locations, facilities, roads, recontoured <u> </u>
Compaction alleviation <u> </u>	Dust and erosion control <u> </u>
Non cropland: Revegetated 80% <u> </u>	Cropland: perennial forage <u> </u>
Weeds present <u> </u>	Subsidence <u> </u>
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% <u> </u>	
TRANSECT RESULTS OF REFERENCE AREA% <u> </u>	
TOTAL % OF DESIRABLE VEGETATION COVER <u> </u>	
VEGETATIVE COVER <u> </u>	
Comment:	<u> </u>
Corrective Action:	<u> </u>
	Date <u> </u>
Overall Final Reclamation <u> </u>	Well Release on Active Location <input type="checkbox"/>
	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion is occurring where concentrated stormwater flows off of the eastern and southern edges of the working area. Headcut channel is forming in the southeastern portion of the project area, and an erosional channel is forming in the southern portion of the project area. See attached photos.</p> <p>Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Headcut in the southeastern portion of the project area needs to be stabilized to prevent further head-cutting.</p>						Date: 07/07/2017
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601597	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162509