



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*), smooth brome (*Bromus inermis*), and dropseed (*Sporobolus* sp.)



Photo 3: View of erosion occurring within the northern portion of the project area facing westward. Stormwater controls need to be installed to de-energize flows.



Photo 4: View of northern diversion facing eastward, damaged with deep ruts and disturbed soil. Diversion needs repair and stormwater controls.