

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2017

Submitted Date:

06/05/2017

Document Number:

680601600**FIELD INSPECTION FORM**

Loc ID 325501 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email               | Comment                         |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre |       | Sabre.Beebe@bp.com  | <a href="#">All Inspections</a> |
| ,            |       | SanJuanCOGCC@bp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 214901      | WELL | PR     | 03/22/1988  | GW         | 067-06505 | SHOEMAKER 01-34 1 | RI          |

**General Comment:**

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable. Corrective action dates are based off of when the inspection is submitted.](#)



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by grassland and ponderosa pine woodland, with a semi-rural home south of the project area.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment What appears to be surface owner vehicles and equipment are stored in the southeastern portion of the project area.Corrective Action Remove debris and equipment or provide a signed surface owner waiver (in accordance with recent guidance document "Rule 1001.c: Reclamation Waivers and Variances") accepting responsibility for materials stored on the well pad. This letter should define areas on the well pad where surface owner equipment will be stored.Date **08/31/2017**

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|   |  |
|---|--|
| 1003b. Area no longer in use? _____ In _____<br>1003c. Compacted areas have been cross ripped? _____<br>1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____<br>Cuttings management: _____<br>1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ In _____<br>Production areas have been stabilized? _____ Segregated soils have been replaced? _____ |  |
|---|--|

**RESTORATION AND REVEGETATION**

Cropland

|                         |                   |                                       |
|-------------------------|-------------------|---------------------------------------|
| Top soil replaced _____ | Recontoured _____ | Perennial forage re-established _____ |
|-------------------------|-------------------|---------------------------------------|

Non-Cropland

|                         |                   |                        |
|-------------------------|-------------------|------------------------|
| Top soil replaced _____ | Recontoured _____ | 80% Revegetation _____ |
|-------------------------|-------------------|------------------------|

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

  

1003 f. Weeds Noxious weeds? \_\_\_\_\_ I \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation      In Process

---

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

  

|   |   |
|---|---|
| Well plugged _____  | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____  | No disturbance /Location never built _____      |
| Access Roads      Regraded _____                              | Contoured _____ Culverts removed _____          |
| Gravel removed _____  |   |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____                                  | Dust and erosion control _____                  |
| Non cropland: Revegetated 80% _____                           | Cropland: perennial forage _____                |
| Weeds present _____   | Subsidence _____                                |

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

  

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|  |                 |                         |                       |               |                          |         |
| <p>Comment: <a href="#">Concentrated stormwater flows in the northern diversion and damage due to vehicle rutting is occurring. See attached photos.</a></p> <p>Corrective Action: <a href="#">Repair northern diversion and apply stormwater controls to de-energize flows and reduce sediment flows.</a></p> <p>Date: 07/07/2017</p> |                 |                         |                       |               |                          |         |
| <p><b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>   |                 |                         |                       |               |                          |         |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 680601601    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162619">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162619</a> |