

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2017

Submitted Date:

05/30/2017

Document Number:

666803190

FIELD INSPECTION FORM

Loc ID 335346 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258296	WELL	PR	09/01/2004	GW	045-07633	JACKSON 15-28	PR
259436	WELL	PR	09/01/2004	GW	045-07725	JACKSON 16-28	PR

General Comment:

2017 Flowline NTO Inspection 1000' Buffer
Shadowing Operator Pressure Testing Team

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Horizontal Heated Separator	# 2				
Comment:	39.492838/-107.669074				
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:	39.492524/-107.669237				
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	At separators				
Corrective Action:					Date:
Type: Plunger Lift	# 2				
Comment:	39.492559/-107.669017				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	200 BBLS	STEEL AST		39.492731,-107.669172
Comment:	<input type="text"/>				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 258296 Type: WELL API Number: 045-07633 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Flowline

#1 Type:Well Site

2 of Lines

Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Natural Gas

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#2 Type:Dump Line

1 of Lines

Flowline Description

Flowline Type: Dump Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Produced Water

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#3 Type:Dump Line

1 of Lines

Flowline Description

Flowline Type: Dump Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Condensate

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing
 Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)
 1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: _____
 Corrective Action: _____ Date: _____

#4	Type:Sales Line	2 of Lines
----	-----------------	------------

Flowline Description
 Flowline Type: Sales Line Size: 2" Material: Carbon Steel
 Variance: Age: Contents: Natural Gas

Integrity Summary
 Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing
 Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)
 1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: _____
 Corrective Action: _____ Date: _____

#5	Type:Process Piping	1 of Lines
----	---------------------	------------

Flowline Description
 Flowline Type: Process Piping Size: Other Material: Carbon Steel
 Variance: Age: Contents: Natural Gas

Integrity Summary
 Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing
 Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)
 1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Supply line to ECB
 Corrective Action: _____ Date: _____

Facility ID: <u>259436</u>	Type: <u>WELL</u>	API Number: <u>045-07725</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: Plunger lift
 Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
Gravel	Pass					
Rip Rap	Pass					
		Ditches	Pass			
		Check Dams	Pass			
		Gravel	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401295999	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158622
666803193	location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158618