

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2017

Submitted Date:

06/06/2017

Document Number:

684903823**FIELD INSPECTION FORM**

Loc ID 449174	Inspector Name: Pesicka, Conor	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10110</u> Name of Operator: <u>GREAT WESTERN OPERATING COMPANY LLC</u> Address: <u>1801 BROADWAY #500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		akraich@adcogov.org	Inspector for Unincorporated Adams County
Mah, Steven		steven.mah@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449164	WELL	DG	03/14/2017		001-09993	Ocho LD 17-367HC	AO
449165	WELL	DG	03/18/2017		001-09994	Ocho LD 17-367HN	AO
449167	WELL	DG	03/16/2017		001-09996	Ocho LD 17-364HC	AO
449172	WELL	DG	03/17/2017		001-10001	Ocho LD 17-365HN	AO

General Comment:

Adams County oil and gas inspector made contact with great western representative on 6/2/17. He was informed tracking issue would be mitigated over the weekend. Tracking issues were still present as of Monday 6/5/17. See attached photos.

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Sign in at shack		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate.

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	West, north, and east side of location have sound walls.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 449164 Type: WELL API Number: 001-09993 Status: DG Insp. Status: AO

Complaint

Comment: [Complaint #: 20442750, 20442753, 20442891](#)

Field Inspector Assigned: C Pesicka

Well Number: 05- Location #: 449174

Inspection Document #: 684903823

Nature of complaint: Tracking, Sound

If Sound GPS Coordinates of Survey Location: 39.98481, -104.91589

Inspection Observations:

An inspection of the above location was conducted with focus on tracking and sound. A sound study was performed 06/06/17 at the indicated location. Weather conditions included wind speeds of 3-4mph with ambient temperatures of 65 ° F, sound survey was run 350' from west of location from 9:30am to 10:30am. Photo of sound survey location attached. The sound survey resulted in an LeqA of 57 dB, which is in compliance with rule 802.. Inspection of the site found stormwater BMP failures in the tracking pad, which had exceeded its capacity, resulting in discharge on the roadway. At 06/06/17 at 1030, street sweeper made multiple passes on shoulder of highway. C Scale complaint was dismissed via communication with the operator as to operational circumstances. 18A doc#: 200442918, 200442921, 200442923

Corrective Action:

Date:

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: [Well has not been pumped in over 48 hours.](#)

Corrective Action:

Date: _____

Facility ID: 449165 Type: WELL API Number: 001-09994 Status: DG Insp. Status: AO

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: _____

Other: _____

Observation:

Maximum Casing Recorded: 7756 PSI

Tubing: _____

Surface: 0

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 449167 Type: WELL API Number: 001-09996 Status: DG Insp. Status: AO

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: _____

Observation:

Other: _____

Maximum Casing Recorded: 3879 PSI

Tubing: _____

Surface: 0

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 449172 Type: WELL API Number: 001-10001 Status: DG Insp. Status: AO

Well Stimulation

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: 6001 PSI

Tubing: _____

Surface: 0

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Tracking Pad	Fail	Vehicle Tracking	Fail	
Seeding	Pass					
Silt Fences	Pass					

Comment: Tracking pad not installed or inadequately maintained to prevent tracking of material offsite. 48 Hour CA given after discussion with operator.

Corrective Action: Clean out vehicle tracking BMPs on the oil and gas location. If material is tracked onto County or public roads, contact the appropriate authority to address that road.

Date: 06/08/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Operator contacted 06/06/17 at 0800 about vehicle tracking.	pesickac	06/06/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401301364	Site photos	Ocho060617.pdf
684903825	Sound study report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163631