

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2017

Submitted Date:

06/06/2017

Document Number:

673715559

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
320785 \_\_\_\_\_ Sherman, Susan \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10618  
Name of Operator: BISON OIL & GAS LLC  
Address: 999 18TH STREET #3370  
City: DENVER State: CO Zip: 80202

**Findings:**

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
O&G, Bison	303-481-2844	ops@bisonog.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204915	WELL	SI	01/01/2017	GW	005-07000	BENNETT A-2	EG

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vault not labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/07/2017
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-481-2844		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	steel panel		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	bermed		
Corrective Action:		Date:	
Type: Flow Line	# 15		

Comment:	IN USE: 1-2" steel riser at wellhead GPS 39.66810, -104.46252; 5-2" steel risers at separator GPS 39.67043, -104.46507; GMR 1-3" steel riser and 1-2" steel riser GPS 39.67043, -104.46516 and 39.67044, -104.46514; 2-2" steel risers at vault GPS 39.670511, -104.46522; tanks, 1-2" hot oil steel riser line GPS 39.67055, -104.46539, East tank 2-2" steel risers GPS 39.67055, -104.46539, West tank 2-2" steel risers GPS 39.67054, -104.46543. Contacted Operator who said that the double riser configuration would be chanded to one riser.			Date:
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On HHS. Need on open pipe ends at vault. Contacted operator about bird protectors.			Date:
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Flow Line	# 2			
Comment:	NOT IN USE: 1-1" steel riser at wellhead, 1-2" steel riser at treater, flagged.			Date:
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Insufficient	Inadequate
Comment:	weeds inside berms			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 07/07/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment: Weeds inside tank battery berms.					
Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.				Date: 07/07/2017	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 204915 Type: WELL API Number: 005-07000 Status: SI Insp. Status: EG

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In since Jan 2017.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715566	Bison Bennett A-2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164350">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164350</a>