

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2017

Submitted Date:

05/26/2017

Document Number:

674200098**FIELD INSPECTION FORM**

Loc ID 434375 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434369	WELL	DG	04/25/2017	LO	123-38121	Waste Connections 3B-29H-M168	DG
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A-29H-M168	DG
434371	WELL	DG	04/28/2017	LO	123-38123	Waste Connections 3D-29H-M168	DG
434372	WELL	DG	04/26/2017	LO	123-38124	Waste Connections 3C-29H-M168	DG
434373	WELL	DG	04/29/2017	LO	123-38125	Waste Connections 3E-29H-M168	DG
434374	WELL	DG	04/30/2017	LO	123-38126	Waste Connections 3G-29H-M168	DG
434378	WELL	DG	04/29/2017	LO	123-38129	Waste Connections 3F-29H-M168	DG

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type:

#

Comment: approx 32' sound walls surround location for sound mitigation

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Field Flare

Comment: Not in use at time of inspection

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 434369 Type: WELL API Number: 123-38121 Status: DG Insp. Status: DG

Facility ID: 434370 Type: WELL API Number: 123-38122 Status: DG Insp. Status: DG

**Complaint**

Comment: Complaint Received May 25, 2017  
Field Inspector Assigned: Jason E. Gomez  
Complaint Received:  
Date: 5-26-2017 Time 1200 Hrs  
Contacted by Complaint Specialist per Complaint Response forms  
Date: 5-26-2017  
Well Number#: Location #: 434375  
Inspection Document #: 674200098  
Nature of complaint: Odor  
Field Inspector Actions:  
On 5-25-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south of the Crestone Peak Resources, Waste Connection drilling pad.  
On 5-26-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints.  
I also went to the addresses of the complainants and walked the area for approx 1hr in the early morning between 6:30 am and 7:30 am and I did not detect any odors off location at that time.  
All information reviewed and site inspection information were submitted to the complaint specialist for further review.  
No violations of COGCC rules were observed at the time of the inspection

Corrective Action:

Date:

**Well Drilling**

**Rig:** Rig Name: Ensign 153 Pusher/Rig Manager: Peter Santos  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI:        Safety Plan: YES

**Drill Fluids Management:**

Lined Pit:        Unlined Pit:        Closed Loop: YES Semi-Closed Loop:         
 Multi-Well: YES Disposal Location: waste connection

Comment:

Corrective Action:

Date:

Facility ID: 434371 Type: WELL API Number: 123-38123 Status: DG Insp. Status: DG

Facility ID: 434372 Type: WELL API Number: 123-38124 Status: DG Insp. Status: DG

Facility ID: 434373 Type: WELL API Number: 123-38125 Status: DG Insp. Status: DG

Facility ID: 434374 Type: WELL API Number: 123-38126 Status: DG Insp. Status: DG

Facility ID: 434378 Type: WELL API Number: 123-38129 Status: DG Insp. Status: DG

--

--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	not in use at time of inspection
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Waddles	Pass	Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401297255	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159697</a>