

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

05/31/2017

Document Number:

674200110

FIELD INSPECTION FORM

Loc ID 331852 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , General | | COGCCinspections@Anadarko.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 266884 | WELL | PR | 09/21/2006 | GW | 123-21399 | BROTEMARKLE 13-13 | EG |

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer Shadowing Operator Identifying and Abandonment Team](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---------------|--|-------|
| | Type WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|--|-------|
| | Type WELLHEAD | | |
| Comment: | AG PANEL | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | | | |
|--------------------|-----|--|--|-------|-----------------|
| | | | | | corrective date |
| Type: Plunger Lift | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 266884 Type: WELL API Number: 123-21399 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action: Date:

BradenHead

Comment: PLUMBED TO SURFACE

Corrective Action: Date:

Flowline

| #1 | Type: | of Lines |
|----|-------|----------|
|----|-------|----------|

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 1-1" STEEL RISER ABANDON PER NTO

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401297262 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159704 |
| 674200111 | 1" ABANDON PER NTO | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159696 |