

Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 1. Overview of location taken at entrance facing southwest.**

Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



Photo 2. Wellhead with active leak and 1 – 2” steel riser



Photo 3. Close up of active leak occurring at wellhead.

Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 4. View of leaking flowline standing at wellhead looking towards tank.**



**Photo 5. Leak 1 of 3.**



Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



Photo 6. Leak 2 of 3.



Photo 7. Leak 3 of 3.

Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



Photo 8. Steel riser into tank. Stained soil below it.



Photo 9. Overgrown berm.