

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

673404671

FIELD INSPECTION FORM

Loc ID 312982 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: 138 PINYON CIR
City: RANGELY State: CO Zip: 81648

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
hinaman, gary	(970) 675-8257	hinaman@lexry.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223159	WELL	PR	09/26/1982	GW	081-06521	MCWILLIAMS 4-31	PR

General Comment:

[2017 Flowline NTO Inspection Statewide](#)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	500 gallon methanol 1000 gallon methanol		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-629-5536

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE: at wellhead: 1 - 2" steel riser at pit: 1 - 2" steel flowline at separator: 2 - 2" steel riser at meter run: 1 - 2" steel riser		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	40.61386, -107.54108		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	NOT IN USE: 3 - 2" steel insulated risers at 40.61391, -107.54092		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	40.61386, -107.54108		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 223159 Type: WELL API Number: 081-06521 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.12.100

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat: <u>40.613750</u>	Long: <u>-107.541070</u>
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____
 Corrective Action: _____ Date: c

Fencing:
 Fencing Type: Livestock Fencing Condition: Adequate
 Comment: _____
 Corrective Action: _____ Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: _____
 Corrective Action: _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____
 Comment: Two pit IDs in database. 112097 and 116597. One pit on location.
 Corrective Action: Work with COGCC environment, 970-871-1963 kris.neidel@state.co.us, to determine which pit ID is appropriate or to close pit if not in use. Date: 09/16/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298378	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160903
673404682	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160866