

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

673404672

**FIELD INSPECTION FORM**

Loc ID 312780 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 45898  
Name of Operator: KAISER-FRANCIS OIL COMPANY  
Address: P O BOX 21468  
City: TULSA State: OK Zip: 74121

**Findings:**

8 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
VanValkenburg, Charlotte		CharlotV@kfoc.net	<a href="#">Official Contact</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222380	WELL	PR	02/28/2006	GW	081-05372	FOX GOV 1-30	PR

**General Comment:**

[2017 Flowline NTO Inspection Statewide](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Unlabeled container at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/03/2017

**Emergency Contact Number:**

Comment:	405-262-5511		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Type: Flow Line		#		
Comment:	IN USE: 1 - 2" steel riser 1 - 1" steel flowline to separator for pump jack motor 1 - 1" poly line from separator to motor			
Corrective Action:			Date:	
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Type: Flow Line		#		
Comment:	NOT IN USE: 1 - 1" steel riser at wellhead			
Corrective Action:			Date:	
Type: Deadman # & Marked		# 4		
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222380 Type: WELL API Number: 081-05372 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Pumping.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298379	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160904</a>
673404683	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160867</a>