

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/01/2017

Submitted Date:

06/01/2017

Document Number:

674200113**FIELD INSPECTION FORM**
 Loc ID 434375 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Precup, Jim		james.precup@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	
Ash, Margaret		margaret.ash@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434369	WELL	DG	04/25/2017	LO	123-38121	Waste Connections 3B-29H-M168	DG
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A-29H-M168	DG
434371	WELL	DG	04/28/2017	LO	123-38123	Waste Connections 3D-29H-M168	DG
434372	WELL	DG	04/26/2017	LO	123-38124	Waste Connections 3C-29H-M168	DG
434373	WELL	DG	04/29/2017	LO	123-38125	Waste Connections 3E-29H-M168	DG
434374	WELL	DG	04/30/2017	LO	123-38126	Waste Connections 3G-29H-M168	DG
434378	WELL	DG	04/29/2017	LO	123-38129	Waste Connections 3F-29H-M168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment: APPROX. 32' SOUND WALLS SURROUND LOCATION FOR SOUND MITIGATION

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	Field Flare
Comment: NOT IN USE AT TIME OF INSPECTION	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 434369	Type: WELL	API Number: 123-38121	Status: DG	Insp. Status: DG
Facility ID: 434370	Type: WELL	API Number: 123-38122	Status: DG	Insp. Status: DG
Facility ID: 434371	Type: WELL	API Number: 123-38123	Status: DG	Insp. Status: DG
Facility ID: 434372	Type: WELL	API Number: 123-38124	Status: DG	Insp. Status: DG
Facility ID: 434373	Type: WELL	API Number: 123-38125	Status: DG	Insp. Status: DG

Complaint

Comment:

Complaint Received May 31, 2017
Field Inspector Assigned: Jason E. Gomez

Complaint Received:
Date: 5-31-2017 Time 1500 Hrs

Contacted by Complaint Specialist per Complaint Response forms
Date: 5-31-2017

Well Number#: Location #: 434375
Inspection Document #: 674200113

Nature of complaint: Odor

Field Inspector Actions:

On 5-31-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south and south west of the Crestone Peak Resources, Waste Connection drilling pad.

On 5-31-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints.

As part of my inspection process I drove thru the neighborhoods indicated on the complaints. While driving through the neighborhood to the south west of the drilling rig I detected an odor which I believed to be coming from the drilling rig. I exited my vehicle and walked on Vista Park way and Driver Lane. At the time I smelled the odor at approx. 1740Hrs the wind appeared to be coming out of the NE.

I advised the Crestone representative Buddy Burke I had detected the odor off location and he indicated he would check and adjust the odor mitigation solution in an attempt to control the odors.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action: Make adjustment to Odor mitigation solution to control odors off location

Date: 06/01/2017

Well Drilling

Rig: Rig Name: ENSIGN 153 Pusher/Rig Manager: BUDDY BURKE
Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES

**Drill Fluids
Management:**Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____Multi-Well: YES Disposal Location: WASTE CONNECTIONComment: _____

Corrective Action: _____ Date: _____

Facility ID: 434374 Type: WELL API Number: 123-38126 Status: DG Insp. Status: DGFacility ID: 434378 Type: WELL API Number: 123-38129 Status: DG Insp. Status: DG

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: NOT IN USE AT TIME OF INSPECTION

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298226	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160752