

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2017

Submitted Date:

06/01/2017

Document Number:

675103650**FIELD INSPECTION FORM**

Loc ID 334094 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275952	WELL	PR	08/11/2005	GW	045-10406	TIPPING 34-5 (OD34)	EG
275954	WELL	PR	12/01/2014	GW	045-10404	TIPPING 27-14 (OD34)	EG
275955	WELL	PR	10/12/2012	GW	045-10403	TIPPING 34-3 (OD34)	EG
281995	WELL	PR	11/26/2014	GW	045-11608	TIPPING 34-4X (OD34)	EG

General Comment:2017 Flowline NTO inspection 1000' buffer

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-625-4209

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:	39.40097/-108.10027		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:	39.40097/-108.10027		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		

Comment:	IN USE; 3-3" steel risers from wells to separators. -2" steel riser from well to separator. 4-2" steel above ground flowlines from wellhead casing valve to gas meter. 4-3" steel risers from gas out separator to sales line. 4-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 2-2" steel risers from separator water/oil dump to tank battery.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	NOT IN USE; 1-2" water/oil dump line next to separator – ties into water/oil dump line to tank battery , identified and capped.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		39.400960,-108.100820
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 275952 Type: WELL API Number: 045-10406 Status: PR Insp. Status: EG**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Well SI at time of inspection - no leaks/venting. Bradenhead/well pressure remotely monitored.

Corrective Action: _____ Date: _____

Flowline

#1 Type: Well Site of Lines

Flowline DescriptionFlowline Type: Well Site Size: _____ Material: _____
Variance: _____ Age: _____ Contents: _____Integrity SummaryFailures: _____ Spills: _____ Repairs Made: _____
Coatings: _____ H2S: _____ Cathodic Protection: _____Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. AbandonmentComment: NOT IN USE; 1-2" water/oil dump line next to separator – ties into water/oil dump line to tank battery , identified and capped.
IN USE; 3-3" steel risers from wells to separators. -2" steel riser from well to separator. 4-2" steel above ground flowlines from wellhead casing valve to gas meter. 4-3" steel risers from gas out separator to sales line. 4-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 2-2" steel risers from separator water/oil dump to tank battery.

Corrective Action: _____ Date: _____

Facility ID: 275954 Type: WELL API Number: 045-10404 Status: PR Insp. Status: EG**Producing Well**Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.

Corrective Action: _____ Date: _____

Facility ID: 275955 Type: WELL API Number: 045-10403 Status: PR Insp. Status: EG**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Well SI at time of inspection - no leaks/venting. Bradenhead/well pressure remotely monitored.

Corrective Action: _____ Date: _____

Facility ID: 281995 Type: WELL API Number: 045-11608 Status: PR Insp. Status: EG

Idle Well		
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE
Comment:	<div>Well SI at time of inspection - no leaks/venting. Bradenhead/well pressure remotely monitored.</div>	
Corrective Action:	<div></div>	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Retention Ponds	Pass					
Berms	Pass					
Gravel	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401297952	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160359
675103651	Flow line photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160322