

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

678800210**FIELD INSPECTION FORM**

Loc ID 318324 Inspector Name: LEONARD, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	(303) 825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241106	WELL	PR	05/25/1995	OW	123-08894	JAMES S HALEY TRUSTEE B 4	EG

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign washed out difficult to read. See attached photo		
Corrective Action:	Rule 210. e. Operators shall maintain signs in a legible condition, and shall replace damaged or vandalized signs within sixty (60) days.	Date:	08/01/2017

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	TRASH		
Comment:	Pile of trash to southeast of wellhead		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	06/15/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Angle Iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electrical Transformers, Power Boxes		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	1 - 2" flowline riser at wellhead. GPS 40.07869/-104.97695		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Standard		
Corrective Action:		Date:	

Venting:			
Yes/No			

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241106 Type: WELL API Number: 123-08894 Status: PR Insp. Status: EG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well shut in at time of inspection

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298037	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160530
678800211	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160524